

Product Bulletin

VST EVR Breakaway Update
Part Number: VSTA-EVR-SBK

09.30.09



Vapor Systems Technologies, Inc.
650 Pleasant Valley Drive
Springboro, Ohio 45066 (USA)
Toll Free: 1-888-878-4673
Phone: 937-704-9333
Fax: 937-704-9443
www.vsthose.com

VST EVR Breakaway Update

It has been reported to VST that illegal field repairs with unauthorized components of VST part number VSTA-EVR-SBK are occurring throughout California. This type of illegal activity creates a liability concern and safety issue for GDF owners, contractors, distributors, and VST. VST will pursue all violators conducting this type of illegal activity and hold them accountable to the strictest letter of the law. Clearly these type repairs are not authorized by UL, The California State Fire Marshal or CARB, let alone VST.

At the same time, VST has been working through the proper regulatory channels in order to provide a safe field repair program. Although an exact time table has not been established, VST is dedicated to providing the lowest cost approach to enhanced vapor recovery EVR.

As an interim step to an authorized field repair program, VST will offer the marketplace a credit opportunity for every returned VSTA-EVR-SBK (both halves in a VSTA-EVR-SBK box) that has been involved in a drive-off episode. This program will be coordinated between VST and our authorized Distribution network throughout California. A list of authorized VST Distributors may be found on our website at www.vsthose.com – or a direct page link at <http://www.vsthose.com/distributors/index.html>

Why let your customers take the safety risk; let the VST core program offer an interim cost reduction program while the approval process is in motion.